Engineering has reviewed the plans for the NHRMC Employee Parking Deck project submitted November 16, 2016 and have the following comments:

SW Permit Application

1. The chart on page 3, line item #9, lists the sidewalk as pervious instead of impervious. You can resubmit a new page 3 or I can revise this sheet with your permission.

Plans

- 2. Sheet C-1: Add the removal hatch pattern to the existing curb & gutter from the proposed southern flare driveway intersection to the existing inlet 4 along Pharmacy Drive including the existing concrete driveway to better illustrate what is to be removed in this area.
- 3. Sheet C-1: Add the existing pipe size and material of the pipe to be removed between inlet 4 and 5.
- 4. Sheet C-2: All proposed pipes need to be labeled with pipe diameter, pipe length, pipe slope and pipe material.
- 5. Sheet C-2: Label the existing pipe size, length and slope between inlet 4 and JB-5A.
- 6. Sheet c-2: The invert for JB-5A does not match the invert provided in the calculations.
- 7. Sheet C-2: Please make sure all existing pipes are shown and labeled to verify information provided in the calculations.
- 8. Sheet C-2: Will the portion of the proposed 12" PVC pipe between JB-5B and JB-5A that is underneath the proposed driveway entrance to the parking depth withstand the traffic loads it will experience?
- 9. Sheet C-2: Existing inlet labels are difficult to locate and read.
- 10. Sheet C-2: There appears to be a negative slope between existing inlets 17 and 18.
- 11. Please provide a drainage area inlet map.
- 12. Make certain that all city standard details are the most recent pdf version downloaded from the city website.

Please submit electronically one copy of each revised plan sheet and page 3 of the application to Engineering for additional review. Please call or email if there are any questions. Thank you.