

Engineering has reviewed the plans for Home 2 Suites by Hilton project submitted March, 7th 2019 and have the following comments:

Plans:

- 1) Site Plan (C2): Draw sidewalk behind Commercial Driveway (Eastwood Service Lane) flares per SD 3-03.3
- 2) Site Plan (C10): Detail #5: 1' Sump does not corresponded with inlet labels (bottom box) provided on grading plan.
- 3) Detail Sheet (C10): Detail #7: Update Emergency Spillway Detail.

Calculations:

- 4) Provide Energy dissipation Calculations. These can be provided as PDFs via email.

No Further Comments. Assure plan revisions have been made prior to submission of Issued For Construction Set.