

Engineering has reviewed the plans for the Peace Baptist Church project submitted March 22, 2019 and have the following comments:

**Plans**

1. The existing grade elevations provided on the Drainage Area Exhibit Map for the boring locations do not agree with the existing topo provided on sheet C-1. Coupled with the email I received on January 23, 2019 from you that revealed issues you were having meeting the 24" separation from the SHWT with the site grading, I am not totally confident that the separation requirement has been satisfied. Can you provide more information that solidifies the requirement being met?
2. No further comments.

Please call or email if there are any questions. Thank you.