



Public Services

Engineering
212 Operations Center Drive
Wilmington, NC 28412
910 341-7807
910 341-5881 fax
wilmingtonnc.gov
Dial 711 TTY/Voice

September 10, 2018

Mr. Jeff Kentner, President & CEO State Street Companies SSG-1, LLC P.O. Box 12477 Charlotte, NC 28220

Subject:

Stormwater Management Permit No. 2017038R2

Airlie at Wrightsville Sound High Density Development

Dear Mr. Kentner:

The City of Wilmington Engineering Division has received a request for a revision to the Stormwater Management Permit for Airlie at Wrightsville Sound. Having reviewed the application and all supporting materials, the City of Wilmington has determined that the proposed revision meets the requirements of the City of Wilmington's Comprehensive Stormwater Ordinance.

The revisions include:

- Site Layout changes impacting impervious surface areas.
- Underground Infiltration Trench redesigns.
- See plans dated August 28, 2018.

Please be aware all terms and conditions of the permit Issued on September 8, 2017 remain in full force and effect. Any additional changes to the approved plans must be approved by this office prior to construction. The issuance of the plan revision does not preclude the permittee from complying with all other applicable statutes, rules, regulations or ordinances which may have jurisdiction over the proposed activity, and obtaining a permit or approval prior to construction.

The revised stamped, approved stormwater management drawings will be released for construction by the Wilmington Planning Division under separate cover. Please replace any old plan sheets from the approved set with the new, revised sheet. An electronic copy of the approved drawing set, permit, application and supplementary documents will be maintained by the Wilmington Engineering Division. If you have any questions, or need additional information, please contact Richard Christensen at (910) 341-7813 or richard.christensen@wilmingtonnc.gov

Sincerely,

for Sterling Cheatham, City Manager

City of Wilmington

cc: Richard Collier, PE, McKim & Creed Inc.

Brian Chambers, Senior Planner, City of Wilmington





Public Services
Engineering
212 Operations Center Dr
Wilmington, NC 28412
910 341-7807
910 341-5881 fax
wilmingtonnc.gov
Dial 711 TTY/Voice

STORMWATER MANAGEMENT PERMIT APPLICATION FORM (Form SWP 2.2)

I. GENERAL INFORMATION

1.	Project Name (subdivision, facility, or establishment name - should be consistent with project name on plans, specifications, letters, operation and maintenance agreements, etc.):
	Airlie at Wrightsville Sound - 49 Lot Subdivision
2.	Location of Project (street address): 315 Airlie Road
	City: Wilmington County: New Hanover Zip: 28403
3.	Directions to project (from nearest major intersection):
	From north bound Oleander Drive (US-76), turn right on to Airlie Road. The project is located on the left
	approximately 0.25 miles from the intersection.
II.	PERMIT INFORMATION
1.	Specify the type of project (check one): Low Density High Density Drains to an Offsite Stormwater System Drainage Plan Other If the project drains to an Offsite System, list the Stormwater Permit Number(s):
	City of Wilmington: State – NCDENR/DWQ:
2.	Is the project currently covered (whole or in part) by an existing City or State (NCDENR/DWQ) Stormwater Permit? Yes No If yes, list all applicable Stormwater Permit Numbers:
	City of Wilmington: 2017038R1 State – NCDENR/DWQ:
3.	Additional Project Permit Requirements (check all applicable): CAMA Major Sedimentation/Erosion Control NPDES Industrial Stormwater 404/401 Permit: Proposed Impacts 0.336 acres
	If any of these permits have already been acquired please provide the Project Name, Project/Permit Number, issue date and the type of each permit:
	NHC Grading Permit #28-17: and USACE SAW-2017-1448



III. CONTACT INFORMATION

1.	designated government official, individual, etc. who owns the project):
	Applicant / Organization:Airlie at Wrightsville Sound, LLC
	Signing Official & Title:Elizabeth K. Brinkman, Member
	a. Contact information for Applicant / Signing Official:
	Street Address: P.O. Box 12477
	City: Charlotte State: NC Zip: 28220
	Phone: (704) 372-3703 Fax: (704) 973-9804 Email: bbrinkman@statestreetco.com
	Mailing Address (if different than physical address):
	City:State:Zip:
	b. Please check the appropriate box. The applicant listed above is:
	The property owner (Skip to item 3) Lessee* (Attach a copy of the lease agreement and complete items 2 and 2a below) Purchaser* (Attach a copy of the pending sales agreement and complete items 2 and 2a below) Developer* (Complete items 2 and 2a below.)
2.	Print Property Owner's name and title below, if you are the lessee, purchaser, or developer. (This is the person who owns the property that the project is on.)
	Property Owner / Organization:
	Signing Official & Title:
	a. Contact information for Property Owner:
	Street Address:
	City:State:Zip:
	Phone:Fax:Email:
	Mailing Address (if different than physical address):
	City:State:Zip:
3.	(Optional) Print the name and title of another contact such as the project's construction supervisor or another person who can answer questions about the project:
	Other Contact Person / Organization:
	Signing Official & Title:



a. Contact information for person listed in	item 3 above:		
Street Address:			
City:	State:Zip:		
Phone:Fax:	Email:		
	ddress):		
	State:Zip:		
City.	Statezip		
V. PROJECT INFORMATION			
I. In the space provided below, briefly summarize	how the stormwater runoff will be treated.		
Stormwater is treated by use if underground infiltration	on trenches, an infiltration basin, and a storm filter.		
	,		
2. Total Property Area: <u>514,434</u> square feet			
3. Total Coastal Wetlands Area: <u>0</u> sq	uare feet		
4. Total Surface Water Area:osquar	e feet		
5. Total Property Area (2) – Total Coastal Wetland	ds Area (3) – Total Surface Water Area (4) = To		
Project Area: <u>514,434</u> square feet.	(,,		
6. Existing Impervious Surface within Property Are	ea: <u>6,388</u> square feet		
7. Existing Impervious Surface to be Removed/De	emolished: 6,388 square feet		
Existing Impervious Surface to Remain:0	square feet		
Total Onsite (within property boundary) Newly Constructed Impervious Surface (in square feet):			
Buildings/Lots	231,823		
Impervious Pavement	44,112		
Pervious Pavement (adj. total, with 0 % credit	applied) 17,865 *		
Impervious Sidewalks	19,353		
Pervious Sidewalks (adj. total, with % credit	applied) 0		
Other (describe) Mail Kiosk and Fire Pit	500		
Future Development	0		
Total Onsite Newly Constructed Impervious Surf	ace 313,653		
* 8,634 sf of additional Pervious Concrete is receiving 10	00% Pervious Credit under impervious table.		
10. Total Onsite Impervious Surface			
(Existing Impervious Surface to remain + Onsite Newly Co	onstructed Impervious Surface) = <u>313,653</u> square		
11. Project percent of impervious area: (Total Onsite I	mpervious Surface / Total Project Area) x100 = 60.97		
The state of the s			



12. Total Offsite Newly Constructed Impervious Area (improvements made outside of property boundary, in square feet):

Impervious Pavement		1,898
Pervious Pavement (adj. total, with	% credit applied)	
Impervious Sidewalks		3,610
Pervious Sidewalks (adj. total, with	% credit applied)	
Other (describe)		
Total Offsite Newly Constructed Impe	5,508	

13. Total Newly Constructed Impervious Surface		
(Total Onsite + Offsite Newly Constructed Impervious Surface) = _	319, 161	square feet

14. Complete the following information for each Stormwater BMP drainage area. If there are more than three drainage areas in the project, attach an additional sheet with the information for each area provided in the same format as below. Low Density projects may omit this section and skip to Section V.

Basin Information	BMP#A	BMP#B	BMP# C
Receiving Stream Name	Bradley Creek	Bradley Creek	Bradley Creek
Receiving Stream Index Number	18-87-24-4-(2)	18-87-24-4-(2)	18-87-24-4-(2)
Stream Classification	S.C.:#	S.C. : #	S.C. : #
Total Drainage Area (sf)	99,374	83,635	234,152
On-Site Drainage Area (sf)	99,374	83,635	234,152
Off-Site Drainage Area (sf)	0	0	0
Total Impervious Area (sf)	53, 094	51,213	167,680
Buildings/Lots (sf)	47,839	45,427	108,086
Impervious Pavement (sf)	614	0	34,837
Pervious Pavement (sf)	2,168 *	4,589	11,108
Impervious Sidewalks (sf)	2,173	997	13,649
Pervious Sidewalks (sf)	0	0	0
Other (sf)	300	200	0
Future Development (sf)	0	0	0
Existing Impervious to remain (sf)	0	0	0
Offsite (sf)	0	0	0
Percent Impervious Area (%)	53.43%	61.23%	71.67%

^{* 8,634} sf of additional Pervious Concrete is receiving 100% Pervious Credit BMP-A DA only.

15. How was the off-site impervious area listed above determined? Provide documentation:



BMP Drainage area information (continued)

Basin Information	StormFilter BMP # D	Infiltration Basin BMP # F	Pervious Concrete BMP # PC
Receiving Stream Name	Bradley Creek	Bradley Creek	Located within DA-A
Receiving Stream Index Number	18-87-24-4-(2)	18-87-24-4-(2)	(100% Credit for BUA)
Stream Classification	SC:#	SC:#	
Total Drainage Area (sf)	50937	24092	0
On-Site Drainage Area (sf)	50937	24092	
Off-Site Drainage Area (sf)	0	0	
Total Impervious Area (sf)	26549	15117	U (8634)
Buildings/Lots (sf)	15354	15117	0
Impervious Pavement (sf)	8661	0	0
Pervious Pavement, 100 % credit (sf)	0	0	0 (8634)
Impervious Sidewalks (sf)	2534	0	0
Pervious Sidewalks, % credit (sf)	0	0	0
Other (sf)	0	0	0
Future Development (sf)	0	0	0
Existing Impervious to remain (sf)	0	0	0
Offsite (sf)	0	0	0
Percent Impervious Area (%)	52.12%	62.75%	0
Basin Information	(Type of BMP) BMP #	(Type of BMP) BMP #	(Type of BMP) BMP #
Receiving Stream Name			
Receiving Stream Index Number			
Stream Classification			
Total Drainage Area (sf)	0	0	0
On-Site Drainage Area (sf)			
Off-Site Drainage Area (sf)			
Total Impervious Area (sf)	0	0	0
Buildings/Lots (sf)			
Impervious Pavement (sf)			
Pervious Pavement, % credit (sf)			
Impervious Sidewalks (sf)			
Pervious Sidewalks, % credit (sf)			
Other (sf)			
Future Development (sf)			
Existing Impervious to remain (sf)			
Offsite (sf)			
Percent Impervious Area (%)			

8-17-18 -pac



V. SUBMITTAL REQUIREMENTS

- Supplemental and Operation & Maintenance Forms One applicable City of Wilmington Stormwater BMP supplement form and checklist must be submitted for each BMP specified for this project. One applicable proposed operation and maintenance (O&M) form must be submitted for each type of stormwater BMP. Once approved, the operation and maintenance forms must be referenced on the final plat and recorded with the register of deeds office.
- 2. Deed Restrictions and Restrictive Covenants For all subdivisions, outparcels, and future development, the appropriate property restrictions and protective covenants are required to be recorded prior to the sale of any lot. Due to variability in lot sizes or the proposed BUA allocations, a table listing each lot number, lot size, and the allowable built-upon area must be provided as an attachment to the completed and notarized deed restriction form. The appropriate deed restrictions and protective covenants forms can be downloaded at the link listed in section V (3). Download the latest versions for each submittal.

In instances where the applicant is different than the property owner, it is the responsibility of the property owner to sign the deed restrictions and protective covenants form while the applicant is responsible for ensuring that the deed restrictions are recorded.

By the notarized signature(s) below, the permit holder(s) certify that the recorded property restrictions and protective covenants for this project, if required, shall include all the items required in the permit and listed on the forms available on the website, that the covenants will be binding on all parties and persons claiming under them, that they will run with the land, that the required covenants cannot be changed or deleted without concurrence from the City of Wilmington, and that they will be recorded prior to the sale of any lot.

3. Only complete application packages will be accepted and reviewed by the City. A complete package includes all of the items listed on the City Engineering Plan Review Checklist, including the fee. Copies of the Engineering Plan Review Checklist, all Forms, Deed Restrictions as well as detailed instructions on how to complete this application form may be downloaded from:

http://www.wilmingtonnc.gov/PublicServices/Engineering/PlanReview/StormwaterPermits.aspx

The complete application package should be submitted to the following address:

City of Wilmington – Engineering Plan Review Section 212 Operations Center Dr Wilmington, NC 28412



VI. CONSULTANT INFORMATION AND AUTHORIZATION

1.	Applicant: Complete this section if you wish to designate authority to another individual and/or firm (such as a consulting engineer and /or firm) so that they may provide information on your behalf for this project (such as addressing requests for additional information).
	Consulting Engineer: Richard M. Collier, PE
	Consulting Firm: McKim & Creed, Inc.
	a. Contact information for consultant listed above:
	Mailing Address: 243 North Front Street
	City: Wilmington State: NC Zip: 28401
	Phone: (910) 343-1048 Fax: (910) 251-8282 Email: rcollier@mckimcreed.com
VII	PROPERTY OWNER AUTHORIZATION (If Section III(2) has been filled out, complete this section)
own pers liste pro the stor	continuous type name of person listed in Contact Information, item 2)
def Wil res Cha vali	signated agent (entity listed in Contact Information, item 1) dissolves their company and/or cancels or aults on their lease agreement, or pending sale, responsibility for compliance with the City of mington Stormwater Permit reverts back to me, the property owner. As the property owner, it is my ponsibility to notify the City of Wilmington immediately and submit a completed Name/Ownership ange Form within 30 days; otherwise I will be operating a stormwater treatment facility without a d permit. I understand that the operation of a stormwater treatment facility without a valid permit is a ation of the City of Wilmington Municipal Code of Ordinances and may result in appropriate enforcement including the assessment of civil penalties.
SI	EAL emoldement including the assessment of civil penalities.
	Signature:
	Date:
	I,, a Notary Public for the
	State of, County of, do
	hereby certify that
	personally appeared before me this day of,,



and acknowledge the due execution	r of the application for a stormwater permit. Witness my hand and official seal,
My commission expires: 12/19/	20,22
VIII. APPLICANT'S CERTIFIC	CATION
that the information included on that the project will be constructed restrictions and protective covers	Contact Information, item 1), Elizabeth K. Brinkman certify this permit application form is, to the best of my knowledge, correct and ed in conformance with the approved plans, that the required deed ants will be recorded, and that the proposed project complies with the requirements of the applicable stormwater rules under.
SEAL NC TARY NC TARY NC TARY NC TARY NC TARY NC TARY NO TARY N	Signature: Ellastic & Bellisman Date: 12918 I, Anthony Holl , a Notary Public for the State of North Corolling, County of Mechlinburg, do hereby certify that Elizabeth Kentner Brink man personally appeared before me this day of June , 2018, and acknowledge the due execution of the application for a stormwater
permit. Witness my hand and official	erseal,
My commission expires: 12/19	/2022

Permit No.	
	(to be provided by DWQ)

INFILTRATION TRENCH SUPPLEMENT

This form must be filled out, printed and submitted.

The Required Items Checklist (Part III) must be printed, filled out and submitted along with all of the required information.

I. PROJECT INFORMATION			
Project name	Airlie at Wrightsville Sound		
Contact person	Richard M. Collier, PE		计算数据数据数据数据数据数据数据数据数据数据数据数据数据数据数据数据数据数据数据
Phone number	910-343-1048		
Date	8/10/2018		
Drainage area number	A		
II. DESIGN INFORMATION			
Site Characteristics			
Drainage area	99,374.00 ft ²		
Impervious area	53,094.00 ft ²		
Percent impervious	53.4%%		
Design rainfall depth	1.50 in		
Peak Flow Calculations			
1-yr, 24-hr rainfall depth	in		
1-yr, 24-hr intensity	in/hr		MEGELVEN
Pre-development 1-yr, 24-hr discharge	ft ³ /sec		EGE VE
Post-development 1-yr, 24-hr discharge	ft ³ /sec		
Pre/Post 1-yr, 24-hr peak flow control	ft ³ /sec		AUG 1 6 2018
Storage Volume: Non-SA Waters			D D
Minimum volume required	6,594.00 ft ³		FALOIRIFEDIA
Volume provided	7,675.00 ft ³	OK for non-SR waters	ENGINEERING
Storage Volume: SA Waters			
1.5" runoff volume	ft ³		
Pre-development 1-yr, 24-hr runoff volume	ft ³		
Post-development 1-yr, 24-hr runoff volume	ft^3		
Minimum volume required	ft ³		
Volume provided	ft ³		
Soils Report Summary			
Soil type	Baymeade		
Infiltration rate	2.97 in/hr	_	
SHWT elevation	12.25 fmsl		
Trench Design Parameters			
Drawdown time	0.16 days	OK	
Perforated pipe diameter	34.00 in		
Perforated pipe length	367.00 ft		
Number of laterals	5		
Stone type (if used)	#57		
Stone void ratio	0.4		
Stone is free of fines?	Y (Y or N)	OK	

			Permit No.	
			744 - 460 - 460 (1896), 10 (1896), 14 (1896) (1897) (1896)	(to be provided by DWQ)
Trench Elevations				
Bottom elevation	14.25 fmsl	OK		
Storage/overflow elevation	16.40fmsl			
Top elevation	17.58 fmsl			
Trench Dimensions				
Length (long dimension)	115.00 ft			
Width (short dimension)	58.40 ft			
Height (depth)	3.33 ft	OK		
Additional Information				
Maximum volume to each inlet into the trench?	ac-in			
Length of vegetative filter for overflow	ft			
Number of observation wells	2	OK		
Distance to structure	15.00 ft	OK		
Distance from surface waters	115.00 ft	OK		
Distance from water supply well(s)	ft			
Separation from impervious soil layer	2.00 ft	OK		
Depth of naturally occuring soil above SHWT	2.00 ft	OK		
Bottom covered with 4-in of clean sand?	Y (Y or N)	OK		
Proposed drainage easement provided?	Y (Y or N)	OK		
Capures all runoff at ultimate build-out?	Y (Y or N)	OK		
Bypass provided for larger storms?	Y (Y or N)	OK		
Trench wrapped with geotextile fabric?	Y (Y or N)	OK		
Drotrootmont device provided	Company			

Sump

Pretreatment device provided

Permit No	
	(to be provided by DWQ)

INFILTRATION TRENCH SUPPLEMENT

This form must be filled out, printed and submitted.

The Required Items Checklist (Part III) must be printed, filled out and submitted along with all of the required information.

I. PROJECT INFORMATION		
Project name	Airlie at Wrightsville Sound	
Contact person	Richard M. Collier, PE	
Phone number	910-343-1048	
Date	7/2/2018	
Drainage area number	B	
II DESIGN INFORMATION		1000000
II. DESIGN INFORMATION Site Characteristics		
Drainage area	83,635.00 ft ²	
Impervious area	51,213.00 ft ²	
Percent impervious	61.2% %	
Design rainfall depth	1.50 in DECEIN/EI	1
Peak Flow Calculations	<u> </u>	
1-yr, 24-hr rainfall depth	in	
1-yr, 24-ii rainiali depth 1-yr, 24-hr intensity	in/hr AUG 1 6 2018	
Pre-development 1-yr, 24-hr discharge	ft ³ /sec	
Post-development 1-yr, 24-hr discharge	5 No. 10 Per 10	
Pre/Post 1-yr, 24-hr peak flow control	ft³/sec ENGINEERING	
Storage Volume: Non-SA Waters	II / 360	et in from your
Minimum volume required	6,284.00 ft ³	
Volume provided	6,665.00 ft ³ OK for non-SR waters	
•	[[OK IOI HOTE-SIX WATERS	
Storage Volume: SA Waters 1.5" runoff volume	ft ³	
Pre-development 1-yr, 24-hr runoff volume	π ft ³	
Post-development 1-yr, 24-hr runoff volume	t table to the state of the sta	
Minimum volume required	ft ³	
Volume provided	ft ³	
Soils Report Summary	Burker and present about the second s	
Soil type	Seagate	
Infiltration rate	4.48 in/hr	
SHWT elevation	12.50 fmsl	
Trench Design Parameters		
Drawdown time	0.22 days OK	
Perforated pipe diameter	51.00 in	
Perforated pipe length	185.00 ft	
Number of laterals	3	
Stone type (if used)	#57	
Stone void ratio	0.4	
Stone is free of fines?	Y (Y or N) OK	
	- Company	

			Permit No	
				(to be provided by DWQ)
Trench Elevations				
Bottom elevation	14.50 fmsl	OK		
Storage/overflow elevation	18.35 fmsl			
Top elevation	19.00 fmsl			
Trench Dimensions				
Length (long dimension)	185.00 ft			
Width (short dimension)	14.25 ft			
Height (depth)	4.50 ft	OK		
Additional Information				
Maximum volume to each inlet into the trench?	ac-in			
Length of vegetative filter for overflow	ft			
Number of observation wells		OK		
Distance to structure	15.00 ft	OK		
Distance from surface waters	585.00 ft	OK		
Distance from water supply well(s)	N/A ft	OK		
Separation from impervious soil layer	2.00 ft	OK		
Depth of naturally occuring soil above SHWT	2.00 ft	OK		
Bottom covered with 4-in of clean sand?	Y (Y or N)	OK		
Proposed drainage easement provided?	Y (Y or N)	OK		
Capures all runoff at ultimate build-out?	Y (Y or N)	OK		
Bypass provided for larger storms?	Y (Y or N)	OK		
Trench wrapped with geotextile fabric?	Y (Y or N)	OK		
Donton store and donton and doub	THE RESERVE OF THE PARTY OF THE			

Sump

Pretreatment device provided

Permit No.	
	(to be provided by DWQ)

INFILTRATION TRENCH SUPPLEMENT

This form must be filled out, printed and submitted.

The Required Items Checklist (Part III) must be printed, filled out and submitted along with all of the required information.

I. PROJECT INFORMATION			
Project name	Airlie at Wrightsville Sound		
Contact person	Richard M. Collier		的起源的发展的表现的表现的表现的
Phone number	910-343-1048		
Date	8/10/2018		
Drainage area number	C		
II. DESIGN INFORMATION			
Site Characteristics			
Drainage area	234,152.00 ft ²		
Impervious area	167,680.00 ft ²		
Percent impervious	71.6% %		
Design rainfall depth	1.50 in		E CELVED
Peak Flow Calculations			I SEIVE IN
1-yr, 24-hr rainfall depth	in		
1-yr, 24-hr intensity	in/hr		AUG 6 2018
Pre-development 1-yr, 24-hr discharge	ft ³ /sec		had had
Post-development 1-yr, 24-hr discharge	ft ³ /sec		E-010 In Italian Parks
Pre/Post 1-yr, 24-hr peak flow control	ft ³ /sec		ENGINEERING
Storage Volume: Non-SA Waters			annual biological
Minimum volume required	20,327.00 ft ³		
Volume provided	23,367.00 ft ³	OK for non-SR waters	
Storage Volume: SA Waters			
1.5" runoff volume	ft ³		
Pre-development 1-yr, 24-hr runoff volume	ft ³		
Post-development 1-yr, 24-hr runoff volume	ft ³		
Minimum volume required	ft ³		
Volume provided	ft ³		
Soils Report Summary	994		
Soil type	Seagate		
Infiltration rate	12.72 in/hr	<u></u>	
SHWT elevation	7.75 fmsl		
Trench Design Parameters			
Drawdown time	0.10 days	OK	
Perforated pipe diameter	51.00 in	OK	
Perforated pipe length	122.33 ft		
Number of laterals	15		
Stone type (if used)	#57		
Stone void ratio	0.4		
Stone is free of fines?	Y (Y or N)	OK	
	(1.31.11)	Rosella 200	

			Permit No.	
				(to be provided by DWQ)
Trench Elevations				
Bottom elevation	10.00 fmsl	OK		
Storage/overflow elevation	13.74 fmsl			
Top elevation	14.25 fmsl			
Trench Dimensions				
Length (long dimension)	122.33 ft			
Width (short dimension)	76.65 ft			
Height (depth)	4.50 ft	OK		
Additional Information				
Maximum volume to each inlet into the trench?	ac-in			
Length of vegetative filter for overflow	ft			
Number of observation wells	5	OK		
Distance to structure	15.00 ft	OK		
Distance from surface waters	522.00 ft	OK		
Distance from water supply well(s)	N/A ft	OK		
Separation from impervious soil layer	2.00 ft	OK		
Depth of naturally occuring soil above SHWT	1.00 ft	OK		
Bottom covered with 4-in of clean sand?	Y (Y or N)	OK		
Proposed drainage easement provided?	Y (Y or N)	OK		
Capures all runoff at ultimate build-out?	Y (Y or N)	OK		
Bypass provided for larger storms?	Y (Y or N)	OK		
Trench wrapped with geotextile fabric?	Y (Y or N)	OK		
B 1 1 11 1 11 1				

Sump

Pretreatment device provided

Permit No.	
	(to be provided by DWQ)

INFILTRATION BASIN SUPPLEMENT

This form must be filled out, printed and submitted.

The Required Items Checklist (Part III) must be printed, filled out and submitted along with all of the required information.

Project Name	Airlie at Wrightsville Sound		
Contact Person	Richard M. Collier		间于 (
Phone Number	(910) 343-1048		
Date	8/10/2018		
Drainage Area Number	F		
II. DESIGN INFORMATION			
Site Characteristics	PROBRES AND TO PROBRE AND TO PROBRES AND TO PROBRE AND		
Drainage area	24,092.00 ft ²		
Impervious area	15,117.00 ft ²		
Percent impervious	0.63 %		
Design rainfall depth	1.50 in		Transporter from the second second
Peak Flow Calculations			DECEIVER
1-yr, 24-hr rainfall depth	in		
1-yr, 24-hr intensity	in/hr		
Pre-development 1-yr, 24-hr discharge	ft ³ /sec		AUG 1 6 2018
Post-development 1-yr, 24-hr discharge	ft ³ /sec		11 11 100 10 1010
Pre/Post 1-yr, 24-hr peak flow control	ft ³ /sec		
			FNGINEFRING
Storage Volume: Non-SA Waters	1.051.00 63		LIVUINLLINING
Minimum design volume required	1,851.00 ft ³	044	
Design volume provided	2,873.00 ft ³	OK for non-SA waters	
Storage Volume: SA Waters			
1.5" runoff volume	ft ³		
Pre-development 1-yr, 24-hr runoff volume	ft ³		
Post-development 1-yr, 24-hr runoff volume	ft ³		
Minimum required volume	ft ³		
Volume provided	ft ³		
Soils Report Summary			
Soil type	Baymeade		
Infiltration rate	11.56 in/hr	_	
SHWT elevation	8.00 fmsl		
Basin Design Parameters			
Drawdown time	0.06 days	OK	
Basin side slopes	3.00 :1	OK	
Basin bottom elevation	10.00 fmsl	OK	
Storage elevation	11.00 fmsl		
Storage elevation Storage Surface Area	1,277.00 ft ²		
Top elevation	12.00 fmsl		
Basin Bottom Dimensions	.E.oo		
Basin length	55.00 ft		
Basin width	35.00 ft		
Bottom Surface Area	1,277.00 ft ²		

Permit No.______(to be provided by DWQ)

Additional Information

Maximum runoff to each inlet to the basin?
Length of vegetative filter for overflow
Distance to structure
Distance from surface waters
Distance from water supply well(s)
Separation from impervious soil layer
Naturally occuring soil above shwt
Bottom covered with 4-in of clean sand?
Proposed drainage easement provided?
Capures all runoff at ultimate build-out?
Bypass provided for larger storms?
Pretreatment device provided

0.55	ac-in	OK
70.00	ft	OK
50.00	ft	OK
70.00	ft	OK
n/a	ft	OK
2.00	ft	OK
2.00	ft	OK
n/a	(Y or N)	OK
у	(Y or N)	OK
у	(Y or N)	OK
у	(Y or N)	OK
overland vegetat	ive filter	





PERMEABLE PAVEMENT SUPPLEMENT

This form must be completely filled out, printed and submitted.

The Required Items Checklist (Part III) must be printed, filled out and submitted along with all of the required information.

I. PROJECT INFORMATION			
Project Name	Airlie at Wrightsville Sound	and 10 大 0 公司 10 公人 10 公司 10	
Contact Person	Richard M. Collier		
Phone Number	(910) 343-1048		
Date	August 10, 2018 .		
Drainage Area	PPS-A		
II. DESIGN INFORMATION			
Soils Report Summary			
Hydrologic soil group (HSG) of subgrade	A		
Infiltration rate	13.13 in/hr		
Pavement Design Summary		BUA Credit for Permeable Pavement Footprint:	
Permeable Pavement (PP) design type	Infiltration - HSG A/B	80% 75% BUA Credit	
SA of PP being proposed (A _p)	8,634 ft ²		
Resulting BUA counted as impervious for main application form	2,159 • C ft ²		
Adjacent BUA directed to PP (A _c)	8,600 ft ²	OK	
Ratio of A _c to A _p	1.00 (unitless)		
Flow from pervious surfaces is directed away from PP?	Yes	OK	
Design rainfall depth	1.5" in	THE OFTER	
Permeable pavement surface course type	PC	IN EGELVEIN	
Layer 1 - Washed aggregate size (ex. No. 57)	No. 57	Total Control of the	
Layer 1 - Aggregate porosity (n)	0.40 (unitless)	OK DI COOLO	
Layer 2 - Washed aggregate size (ex. No. 57)		AUG 1 6 2018	
Layer 2 - Aggregate porosity (n)	(unitless)	TO AND	
Minimum total aggregate depth for design rainfall (D_{wq})	6.2 in	FRICIALETDIALO	
Drawdown/infiltration time for D _{wq}	0.0 days	OK ENGINEERING	
How is 10-yr, 24-hr storm handled?	infiltrated	Company of the Compan	
Aggregate depth to infiltrate 10-yr, 24-hr storm (D ₁₀)	in		
Drawdown/infiltration time of 10-yr, 24-hr storm	days		
Actual provided total aggregate depth	8.0 in	OK	
Top of aggregate base layer elevation	19.18 fmsl		
Storage elevation of design rainfall depth	19.18 fmsl		
Overflow elevation	19.68 fmsl		
Bottom elevation at subgrade	18.51 fmsl	#REF!	
SHWT elevation	16.51 fmsl		
Underdrain diameter	0 in		

Permit No._____(to be provided by DWQ)

Detention Systems (skip for infiltration systems)	N/A		
Diameter of orifice		in	
Coefficient of discharge (C _D)		(unitless))
Driving head (H _o)		ft	
Storage volume discharge rate (through discharge orifice)	制度可包 法经验	ft³/sec	
Storage volume drawdown time		days	
Pre-development 1-yr, 24-hr peak flow	Mark Commence	ft ³ /sec	
Post-development 1-yr, 24-hr peak flow		ft ³ /sec	
Additional Information			
Slope of soil subgrade at bottom of permeable pavement	0.50	%	OK
Slope of the permeable pavement surface	0.85	%	OK
Construction sequence minimizes compaction to soils?	Yes		OK
Subsoil preparation specified (must select one)	scarified		
Meets industry standards for structural requirements?	Yes		OK
Washed stone is specified for the aggregate?	Yes		OK
Required signage specified on plans?	Yes	N	OK
Number of observation wells provided	1		OK
Distance to structure	8.00	ft	
Distance to surface waters	96.00	ft	OK
Distance to water supply well(s)	N/A	ft	OK

Infiltration Trench Operation and Maintenance Agreement

I will keep a maintenance record on this BMP. This maintenance record will be kept in a log in a known set location. Any deficient BMP elements noted in the inspection will be corrected, repaired or replaced immediately. These deficiencies can affect the integrity of structures, safety of the public, and the removal efficiency of the BMP.


Important maintenance procedures:

- The drainage area of the infiltration trench will be carefully managed to reduce the sediment load to the sand filter.
- The water level in the monitoring wells will be recorded once a month and after every storm event greater than 1.5 inches if in a Coastal County.

The infiltration trench will be inspected **once a quarter and within 24 hours after every storm event greater than 1.5 inches.** Records of operation and maintenance will be kept in a known set location and will be available upon request.

Inspection activities shall be performed as follows. Any problems that are found shall be repaired immediately.

BMP element:	Potential problem:	How I will remediate the problem:
The entire BMP	Trash/debris is present.	Remove the trash/debris.
The grass filter strip or	Areas of bare soil and/or	Regrade the soil if necessary to
other pretreatment area	erosive gullies have formed.	remove the gully, and then plant a
	(MANA)	ground cover and water until it is
		established. Provide lime and a
		one-time fertilizer application.
	Sediment has accumulated to	Search for the source of the
	a depth of greater than six	sediment and remedy the problem if
	inches.	possible. Remove the sediment and
		dispose of it in a location where it
		will not cause impacts to streams or
		the BMP.
The flow diversion	The structure is clogged.	Unclog the conveyance and dispose
structure (if applicable)		of any sediment off-site.
pr Augustus 2 AS	The structure is damaged.	Make any necessary repairs or
	,	replace if damage is too large for
		repair.



BMP element:	Potential problem:	How I will remediate the problem:
The trench	Water is ponding on the	Remove the accumulated sediment
	surface for more than 24	from the infiltration system and
	hours after a storm.	dispose in a location that will not
		impact a stream or the BMP.
	The depth in the trench is	Remove the accumulated sediment
	reduced to 75% of the original	from the infiltration system and
	design depth.	dispose in a location that will not
		impact a stream or the BMP.
	Grass or other plants are	Remove the plants, preferably by
	growing on the surface of the	hand. If pesticide is used, wipe it on
	trench.	the plants rather than spraying.
The observation well(s)	The water table is within one	Contact the DWQ Stormwater Unit
	foot of the bottom of the	immediately at 919-733-5083.
	system for a period of three	-
	consecutive months.	
	The outflow pipe is clogged.	Provide additional erosion
		protection such as reinforced turf
		matting or riprap if needed to
		prevent future erosion problems.
	The outflow pipe is damaged.	Repair or replace the pipe.
The emergency overflow	Erosion or other signs of	The emergency overflow berm will
berm	damage have occurred at the	be repaired or replaced if beyond
	outlet.	repair.
The receiving water	Erosion or other signs of	Contact the NC Division of Water
_	damage have occurred at the	Quality 401 Oversight Unit at 919-
	outlet.	733-1786.

Permit Number:				
(to be pro	vided l	by City o	f Wiln	nington)

I acknowledge and agree by my signature below that I am responsible for the performance of the maintenance procedures listed above. I agree to notify City of Wilmington of any problems with the system or prior to any changes to the system or responsible party.

Project name: Airlie at Wrightsville Sound
BMP drainage basin number: A, B, C
Print name: State Street Companies - SSG-1, LLC (Elizabeth Brinkman/Vice President)
Title: Developer
Address: P.O. Box 12477 Charlotte, NC 28220
Phone:(704) 372-3703
Signature: <u>FUN K BILINOMON</u>
Date: JUly 21, 2017
Note: The legally responsible party should not be a homeowners association unless more than 50% of the lots have been sold and a resident of the subdivision has been named the president. I, Stephan A. Ekekana, a Notary Public for the State of North Carolina, County of Mecklenburg, do hereby certify that Flizabeth Brinkman personally appeared before me this 21th day of July ,2017, and acknowledge the due execution of the forgoing infiltration trench maintenance requirements. Witness my hand and official seal,
Stephan A. EKeKana

STEPHAN A EKEKANG

Alotery Profic
Mecklenburg Co., North Cerolina
My Commission Expires Jan. 27, 2019

William Chianant Chian

SEAL

My commission expires Jan 27, 2019

Infiltration Basin Operation and Maintenance Agreement

I will keep a maintenance record on this BMP. This maintenance record will be kept in a log in a known set location. Any deficient BMP elements noted in the inspection will be corrected, repaired or replaced immediately. These deficiencies can affect the integrity of structures, safety of the public, and the removal efficiency of the BMP.

Important maintenance procedures:

- The drainage area will be carefully managed to reduce the sediment load to the infiltration basin.
- Immediately after the infiltration basin is established, the vegetation will be watered twice weekly if needed until the plants become established (commonly six weeks).
- No portion of the infiltration basin will be fertilized after the initial fertilization that is required to establish the vegetation.
- The vegetation in and around the basin will be maintained at a height of approximately six inches.

After the infiltration basin is established, it will be inspected **once a quarter and within 24 hours after every storm event greater than 1.5 inches**. Records of operation and maintenance will be kept in a known set location and will be available upon request.

Inspection activities shall be performed as follows. Any problems that are found shall be repaired immediately.

BMP element:	Potential problem:	How I will remediate the problem:
The entire BMP	Trash/debris is present.	Remove the trash/debris.
The perimeter of the	Areas of bare soil and/or	Regrade the soil if necessary to
infiltration basin	erosive gullies have formed.	remove the gully, and then plant a
		ground cover and water until it is
	92	established. Provide lime and a
		one-time fertilizer application.
The inlet device: pipe or	The pipe is clogged (if	Unclog the pipe. Dispose of the
swale	applicable).	sediment off-site.
	The pipe is cracked or	Replace the pipe.
	otherwise damaged (if	324
	applicable).	
	Erosion is occurring in the	Regrade the swale if necessary to
	swale (if applicable).	smooth it over and provide erosion
		control devices such as reinforced
		turf matting or riprap to avoid
		future problems with erosion.



BMP element:	Potential problem:	How I will remediate the problem:
The forebay	Sediment has accumulated	Search for the source of the
	and reduced the depth to 75%	sediment and remedy the problem if
	of the original design depth.	possible. Remove the sediment and
		dispose of it in a location where it
		will not cause impacts to streams or
		the BMP.
	Erosion has occurred or	Provide additional erosion
	riprap is displaced.	protection such as reinforced turf
		matting or riprap if needed to
		prevent future erosion problems.
	Weeds are present.	Remove the weeds, preferably by
		hand. If pesticides are used, wipe
		them on the plants rather than
		spraying.
The main treatment area	A visible layer of sediment	Search for the source of the
	has accumulated.	sediment and remedy the problem if
		possible. Remove the sediment and
		dispose of it in a location where it
		will not cause impacts to streams or
		the BMP. Replace any media that
		was removed in the process.
		Revegetate disturbed areas
•	Water is standing more than	immediately. Replace the top few inches of filter
	Water is standing more than 5 days after a storm event.	media and see if this corrects the
	3 days after a storm event.	standing water problem. If so,
		revegetate immediately. If not,
		consult an appropriate professional
		for a more extensive repair.
	Weeds and noxious plants are	Remove the plants by hand or by
	growing in the main	wiping them with pesticide (do not
	treatment area.	spray).
The embankment	Shrubs or trees have started	Remove shrubs or trees
	to grow on the embankment.	immediately.
	An annual inspection by an	Make all needed repairs.
	appropriate professional	•
	shows that the embankment	
	needs repair.	
The outlet device	Clogging has occurred.	Clean out the outlet device. Dispose
		of the sediment off-site.
	The outlet device is damaged	Repair or replace the outlet device.
The receiving water	Erosion or other signs of	Contact the NC Division of Water
	damage have occurred at the	Quality 401 Oversight Unit at 919-
	outlet.	733-1786.

Permit Numl	per:
(to be	provided by City of Wilmington)

I acknowledge and agree by my signature below that I am responsible for the performance of the maintenance procedures listed above. I agree to notify the City of Wilmington of any problems with the system or prior to any changes to the system or responsible party.

Project name: Airlie at Wrightsville Sound
BMP drainage basin number: Basin - F
Print name: Elizabeth K. Brinkman
Title: Member
Address:P.O. Box 12477, Charlotte, NC 28220
Phone:(704) 372-3703
Signature: Eliabath & Building
Date: <u>12918</u>
Note: The legally responsible party should not be a homeowners association unless more than 50% of the lots have been sold and a resident of the subdivision has been named the president. I, Anthony Hill, a Notary Public for the State of, do hereby certify that, do hereby certify that
NOTAR IN THE COMMISSION STORES TO THE BURGE COUNTY IN THE PROPERTY OF THE PRO

My commission expires

Form SW401-Infiltration Basin O&M-Rev.3

Permit Number:	
1	(to be provided by DWO)

StormFilter Operation and Maintenance Agreement

I will keep a maintenance record on this BMP. This maintenance record will be kept in a log in a known set location. Any deficient BMP elements noted in the inspection will be corrected, repaired or replaced immediately. These deficiencies can affect the integrity of structures, safety of the public, and the removal efficiency of the BMP.

Important maintenance procedures:

- The drainage area will be carefully managed to reduce the sediment load to the StormFilter.
- The sedimentation chamber or forebay will be cleaned out whenever sediment depth exceeds six inches.

The StormFilter system will be inspected **quarterly**. Records of operation and maintenance will be kept in a known set location and will be available upon request.

Inspection activities shall be performed as follows. Any problems that are found shall be repaired immediately.

BMP element:	Potential problem:	How I will remediate the problem:
Entire BMP	Trash/debris is present.	Remove the trash/debris.
Adjacent pavement (if applicable)	Sediment is present on the pavement surface.	Sweep or vacuum the sediment as soon as possible.
Flow diversion structure	The structure is clogged.	Unclog the conveyance and dispose of any sediment offsite.
	The structure is damaged.	Make any necessary repairs or replace if damage is too large for repair.
StormFilter Cartridges	Cartridges not performing as designed – see Contech I&M document to determine if cartridge maintenance is required.	Replace cartridges per manufacturer's recommendations.
Outlet device	Clogging has occurred.	Clean out the outlet device. Dispose of the sediment offsite.
	The outlet device is damaged	Repair or replace the outlet device.
Receiving water	Erosion or other signs of damage have occurred at the outlet.	Contact the NC Division of Water Quality 401 Oversight Unit at 919-733- 1786.



Permit Number:	
	(to be provided by DWQ)

All other operation and maintenance activities should be in accordance with Contech's **StormFilter Inspection and Maintenance Procedures** document. Any problems that are found shall be repaired immediately. I acknowledge and agree by my signature below that I am responsible for the performance of the maintenance procedures listed above and have received and understand Contech's **StormFilter Inspection and Maintenance Procedures** document. I agree to notify DWQ of any problems with the system or prior to any changes to the system or responsible party.

Project name: Airlie at Wrightsville Sound
BMP drainage area number: <u>D</u>
Print name: State Street Companies - SSG-1, LLC (Elizabeth Brinkman / Vice President)
Title: Developer
Address: P.O. Box 12477 Charlotte, NC 28220
Phone: (704) 372-3703
Signature: Both & Bringman
Date: 1414 21, 2017
Note: The legally responsible party should not be a homeowners association unless more than 50% of the lots have been sold and a resident of the subdivision has been named the president.
I, Stephan A. Eke Kang
STEPHAN A. EKEKANG Alotsry Predic Mecklenburg Co., North Caroline My Commission Explice Jan. 27, 2019

My commission expires

Permit Number:
(to be provided by DWQ)
Drainage Area / Lot Number:

Permeable Pavement Operation and Maintenance Agreement

I will keep a maintenance record on this BMP. This maintenance record will be kept in a log in a known set location. Any deficient BMP elements noted in the inspection will be corrected, repaired or replaced immediately. These deficiencies can affect the integrity of structures, safety of the public, and the removal efficiency of the BMP.

At all times, the pavement shall be kept free of:

- Debris and particulate matter through frequent blowing that removes such debris, particularly during the fall and spring.
- Piles of soil, sand, mulch, building materials or other materials that could deposit particulates on the pavement.
- Piles of snow and ice.
- Chemicals of all kinds, including deicers.

The permeable pavement will be inspected **once a quarter**. Records of operation and maintenance will be kept in a known set location and will be available upon request.

Inspection activities shall be performed as follows. Any problems that are found shall be repaired immediately.

	BMP element:	Potential problem:	How to remediate the problem:
	The perimeter of the permeable pavement	Areas of bare soil and/or erosive gullies	Regrade the soil if necessary to remove the gully, then plant ground cover and water until established.
DECE NAUG II ENGIN		A vegetated area drains toward the pavement.	Regrade the area so that it drains away from the pavement, then plant ground cover and water until established.
	The surface of the permeable pavement	Trash/debris present	Remove the trash/debris.
		Weeds	Do not pull the weeds (may pull out media as well). Spray them with a systemic herbicide such as glyphosate and then return within the week to remove them by hand. (Another option is to pour boiling water on them or steam them.)
	EERING	Sediment	Vacuum sweep the pavement.
		Rutting, cracking or slumping or damaged structure	Consult an appropriate professional.
	Observation well	Water present more than five days after a storm event	Clean out clogged underdrain pipes. Consult an appropriate professional for clogged soil subgrade.
	Educational sign	Missing or is damaged.	Replace the sign.

Permit Number:	
	(to be provided by DWQ)

I acknowledge and agree by my signature below that I am responsible for the performance of the maintenance procedures listed above. I agree to notify DWQ of any problems with the system or prior to any changes to the system or responsible party.

Project name: Airlie at Wrightsville Sound

BMP drainage area or lot number:

Print name: State Street Companies - SSG-1, LLC (Elizabeth Brinkman/Vice President)

Title: Developer

Address: P.O. Box 12477 Charlotte, NC 28220

Phone: (704) 3721-3703

Signature: Belle Bulle Bulle

Date: JUly 21, 2017

Note: The legally responsible party should not be a homeowners association unless more than 50% of the lots have been sold and a resident of the subdivision has been named the president.

1, Stephan A. Ekekana, a Notary Public for the State of

North Carolina, County of Mecklenburg, do hereby certify that

Elizabeth Brinkman personally appeared before me this day

of July 21, 2017, and acknowledge the due execution of the forgoing

permeable pavement maintenance requirements. Witness my hand and official seal,

SEAL

STEPHAN A. EKEKANG

Notary Profic Mecklenburg Co., North Carolina My Commission Explice Jan. 27, 2019 Stephan A. EKeKang

My commission expires Jan. 27, 2019