

9. The relocated raised crosswalk on Calypso Dr. shall not be located adjacent to the driveway. Vehicles should not be turning on/off the ramp section.
10. The raised crosswalk on Calypso Dr is incorrectly labeled as a “Speed Hump”. Ensure the labels match the new location of the relocated crosswalk.
11. The Van accessible aisle width must be 96” to meet ADA requirements. Some Van accessible spaces are shown with 5’ aisle and some are shown with 8’ aisle width. [[Sec. 18-529\(b\)\(2\) CofW LDC](#)]

MISCELLANEOUS:

- ❖ Transportation Planning Staff reserves the right to review and comment on any additional plans submitted for this development.

Please let me know if you have any questions or if I can be of further assistance as this development moves through the review process.