

NHRMC Critical Support Facility

TRC Planning Review 4/3/20

Brian Chambers, 910.342.2782, brian.chambers@wilmingtonnc.gov

- Plan shows 10", 10", and 12" Magnolias being removed. Tree permit indicates 8", 10", and 12" Magnolias. If plan is correct please provide updated tree permit with the correct trees listed.
- Plan shows 13", 13", 16", 20", and 20" pines being removed. Tree permit table identifies 13", 16", 20", and 28" pines. If plan is correct please provide updated tree permit with the correct trees listed.
- Please identify the 22 trees being saved for tree credits.